

TAŞIMA

- Ürün teslim alınmadan önce üründe veya ambalajında herhangi bir hasar olmadığı kontrol edilmelidir.
- Nakliye sırasında oluşan titreşimler ürünün hasar görmesine neden olabilir. Ürün indirildikten sonra öncelikle sevk basınç kontrolü yapılmalıdır.
- Herhangi bir hasar tespit edilirse derhal THERMOWAY A.Ş. firmasına bilgi verilmelidir.
- Ürün taşınırken aşağıda belirtilen talimatlara ve emniyet kurallarına uyulmalıdır.
- Taşıma işlemi yetkin ve sertifikalı bir personel tarafından yapılmalıdır.
- Yeterli taşıma kapasitesine sahip ekipmanlar kullanılmalıdır.
- Ürün üzerinde belirtilen taşıma noktalarından bağlantı yapılmalıdır.
- Taşıma noktalarında eşit ağırlık dağılımı sağlanmalıdır.
- Taşıma esnasında kollektör ve fanlardan destek alınıp taşınmamalıdır.

Forklift ile taşıma işlemi yapılacaksa forklift bıçaklarının ürüne zarar vermeyeceği şekilde doğru yönde ve gerekli boşluk bırakılarak kaldırmasını kontrol edin

Ürün halat tertibatı ile kaldırılacaksa ürünün zarar görmeyeceği şekilde halat açısını ayarlayarak taşınması gerekmektedir.

Eğer üründe tek halat mekanizması ile istenen açı sağlanamıyorsa görseldeki teçhizatla taşıma yapılması gerekmektedir.




TRANSPORTATION

- Before receiving the product, it should be checked that there is no damage to the product or its packaging.
- Vibrations during transport may cause damage to the product. After the product is lowered, first of all the dispatch pressure control should be done.
- If any damage is detected, THERMOWAY A.Ş. should be informed immediately.
- The following instructions and safety rules must be followed while the product is being transported.
- Transportation should be carried out by a competent and certified staff.
- Equipment with sufficient transport capacity should be used.
- Connection must be made from the transport points indicated on the product.
- Equal weight distribution should be provided at the transport points.
- During transportation product should not be handled from collectors and fans.

If the product is to be transported with forklift, check out the forklift blades are in the correct direction and with the necessary clearance so that the product is not damaged.


If the product is to be lifted with a rope assembly, it must be transported by collimating the rope angle so that the product will not be damaged.

If the desired angle cannot be obtained with a single rope mechanism in the product, it is necessary to transport with the equipment in the image.



DEPOLAMA

- Ürünün çevresel etkilerden ve hava koşullarından korunması için ambalajı ile saklanmalıdır.
- Ürün uzun süre nemli bir ortamda saklanacaksa oluşacak oluşacak su buharı bakır ve lamel yüzeylerde küflenmeye sebep olacağı için ürün nemli ortamdan uzaklaştırılmalı, fanlar her ay en az 2 saat çalıştırılmalıdır.
- Depolama işleminde farklı ambalaj ve ölçüdeki ürünlerin üst üste saklanmasından kaçınılmalıdır.



STORAGE

- The product must be stored in its own packaging to protect it from environmental influences and weather conditions. If the product is to be stored for a long time in a humid environment, the product should be removed from the humid environment, as the water vapor that will form will cause mold on the copper and lamella surfaces, and the fans should be run for at least 2 hours every month.
- In stacking, should be avoided storing products in different packages and sizes on top of each other.

